




Hints to Solve Glazing Difficulties For Help Call 866-315-1929


The most common concerns working with the Silhouette Rimless System are due to these 3 areas:



After you mark the pattern lines on the lens, **RE-CHECK** the pattern marks, the 180 line and the shape so that they all align perfectly.







The holes you have drilled **must** be at 90 degrees to the front surface. If you use the drill gauge guide, it will assure that this happens.